

**Burnsville Heating & Air Conditioning, Inc.**  
3451 West Burnsville Pkwy  
SUITE 120  
Burnsville, MN 55337



**INVOICE**  
*Unpaid*

**Presented to:**  
**Brian Werderitch**  
6432 Red Cedar Dr  
Chaska, MN 55318

**Job #** 22499  
**Job Name** Blowing  
**Invoice #** I-22499-1  
**Technician** Cody Meyer  
**Issue Date** May 15 2024  
**Payment Terms** Upon Receipt  
**Due Date** May 15 2024

**Customer Contact:**  
M: 6129867011  
E: [bdub1228@gmail.com](mailto:bdub1228@gmail.com)

**Service Location:**  
6432 Red Cedar Dr  
Chaska, MN 55318

DESCRIPTION	QTY	AVAILABLE SAVINGS	PRICE
Diagnostic Fee	1	\$40.00	\$175.00
Subtotal			\$175.00
Taxes			\$0.00
<b>Total</b>		<b>\$40.00</b>	<b>\$175.00</b>

**Make Payment**

Sign up for a Maintenance Plan and save \$40.00

**Invoice Notes:**

Found oil residue on suction valve. Leaking from valve/braze joints. Talk to homeowner about having Original company out to replace/fix valve and braze joints. If company does not we can replace valve and refrigerant at flat rate price. 62oz of refrigerant and suction valve. \$350.00 for valve and \$340.00 for refrigerant. \$690.00 Plus 2 hours labor \$320.00 total \$1,010. Customer will reach out if they decide for us to repair.

Model# DX13SN0361AH  
Serial# 2201423451

**Customer Approval:**

I agree to the terms and conditions of this invoice, and that the goods and or services referenced have been provided to my satisfaction.

Signature:



Signature Date/Time: 05/15/2024 03:01PM, EDT